Downstream Authority of the Quapaw Tribe of Oklahoma Regular Meeting January 30, 2013

Meeting Called to Order: 10:12 am

ROLL CALL: John Berrey, Chairman Present

Larry Ramsey, Secretary Present
Ranny McWatters, Treasurer Present
Marilyn Rogers, Member Present
Tamara Smiley, Member Present

### **DECLARATION OF QUORUM:** announced by Larry Ramsey

Bob B, Alan, Tim B, Kent, Chris, Scott, Brock, Ryan, Mike, Ernie, Shawn M, John T (via phone)

Kappa Construction Close Out

Prayer led by Ranny McWatters

### **Reviewed Current Punch List**

See attached

### **AS Builds**

- Digital copies have been provided, getting hard copies next week
- Have "project" copies, MCC and JCJ to review and determine if new copies are needed

### **Reviewed Outstanding Balance**

- See attached
- Next week JCJ/MCC/Roper will have a reevaluated number to present to the DDA for approval

### Marketing Review


### Shawn C

- Bussing
  - o review by year (see attached graph)
  - Competitors offers (see attached spreadsheet)
  - New line runs beginning April 2
    - Nevada-Lamar-Carthage, MO Wednesday run
    - Fayetteville-Springdale, AR Tuesday run
    - Independence-Coffeeville-Chetopa, KS Tuesday run
    - Chanute-Parsons-Oswego, KS Wednesday run
    - Pryor-Vinita, OK Wednesday run
    - This will be an increase of 5 buses a week/20 buses a month. The rides will be free (just like the current SEK and NWA line runs). All of them will receive \$5 in Q Play except AR, they will receive \$10. The package decisions were bases on previous play out of these areas
  - How to fix
    - Need more buses / passengers
      - a. Add line runs / many bus companies have closed doors

- Change Package make more aggressive
- Calculate post-formas based on Actual cost not full retail
- Attending ABA, Just got back from Charlotte, NC
- Branson Partnerships
- Room Cost (\$39 to \$49) based on season and day of week
- QClub/Database
  - Current Active Database 50,000+
    - Total database over 222,000+
    - Carded play 54%
  - Increase the size of database
    - Offer incentive to sign up for club
      - Free Buffet or Q play
    - Points for Play
      - Gives lower end players incentive to join and earn points
      - Currently at a Competitive Disadvantage (by our own choice)
    - Catalog Rewards Program
      - Not mass appeal
      - · Can't put I-Pad in slot machine
      - Has hard cost of roughly \$8,000-\$10,000 per month
      - Savings helps pay for IGT Points for Play Module
    - Early day and late night hot seats (Build Value and Build shoulders)
    - Low end play and earns
    - Floor progressive jackpot
    - Reinvestment Based on Play % and not with a Ceiling limit
    - Platinum Card Rollout (90-10)
      - We will need to demote them
    - Finish out comping program that Jeff started
    - Increase email addresses in club
      - Incentive for giving us your address (Q play)
    - Install Kiosks (Good Ones)
      - Swipe and Wins
      - Electronic Drawings
      - Additional Games
- Promotions
  - Current
    - Currently Planned out Through April
    - Recently Added Brandy Lake 3 weeks ago (Work Load)
    - Good working relationship with QTGA
    - Ability to make changes via email has helped immensely
    - Still need to streamline approval processes
  - Basics
    - Geared towards the masses
    - Frequency Drive (Daily entries)
    - Selling Dreams (What can I win, What would I do If I won?)
    - Interactive and Fun (Build Excitement)


- Wish List
  - Permanent Promotion Location
  - Electronic Entries / Drawings
    - Email guests on how many entries they have
  - Environmental Entertainer (Fun and Excitement)
  - Need Working Space
- Events
  - Larger more exciting events
    - For example Bring in Duck Dynasty Cast, Pawn Stars etc Things that are hot and current
    - Bring Paris Hilton in to open pool at beginning of summer (create buzz in community)
    - Mystery band on Legends stage (KC &the Sunshine Band, Mini Kiss)
    - Décor' on different events (enhance the guest experience)
    - Food cost billed as actual cost
- Advertising
  - o Budget has been reduced by 15% in FY2011 and then again by 20% in FY2012
  - We've recently added packages to drive additional business
    - This allows us to have a call to action on advertisements
  - Creative
    - Added New Graphic Designer
      - Working on Billboard Designs
  - Current Photo shoot being done on New Hotel /Spa/Buffalo Grille/Coffee Shop/Pool/Food
  - o Bounce Back Mailer
  - o Billboard Creative meeting Tues 2/19
- Projects
  - o Platinum Club Launch
  - Website
  - o Billboards
  - On Floor Displays
  - Connect Q
  - o Hold %

Adjourn 4:03 pm



### Competitors Day Bus Packages

	1		Competitors bay			1
RANK	CASINO	REQUIRED TIME ON PROPERTY		FREE PLAY/MATCH PLAY OFFER	FOOD OFFER	CASINO INVESTMENT / GUEST / HOUR
1st	Buffalo Run	6 hours	\$15 per head	\$15 Slot Play & \$20 Match play at Tables	\$5.00	\$9.17
2nd	Cherokee - West Siloam	5 hours	\$20 base plus % of win incentives	\$20 Slot Play	1/2 price buffet	\$9.00
3rd	Buffalo Run	5 hours	\$10 per head	\$10 Slot Play & \$20 Match play at Tables	\$2.50	\$8.50
4th	Stables	6 hours	\$15 per guest	\$25 Slot Play	\$8.00 toward meal purchase	
5th	Prairie Band	6 hours	\$15 per guest	\$20 Slot Play	Free Buffet	\$7.50
6th	Bordertown / Indigo Sky	5 hours	buses with more that 40	\$20 Slot Play -Groups with less than 20 passengers only qualify for \$15 in slot play	\$0.00	\$7.00
7th	Choctaw - Pocola	5 hours	Pays for Entire Cost of Bus/No Per Person Commission	\$10 Slot Play	\$5.00	\$7.00
8th	Prairie Band	4 hours	\$10 per guest	\$15 Slot Play	-	\$6.25
9th	Hard Rock - Tulsa	5 hours	\$10 plus incentives for buses with more than 40 passengers	\$10 Slot Play	\$10 for buffet	\$6.00
10th	Downstream Casino Resort	4 hours	\$10 per guest	\$10 Q Play	-	\$5.00
11th	Downstream Casino Resort Option 1	5 - 6 hour stay	\$15 per guest	\$15 Q Play	-	\$5.00
12th	Downstream Casino Resort Option 2	5 - 6 hour stay	\$15 per guest	\$10 Q Play	\$5 meal points	\$5.00



FY 2010 VGT machines made up 12.22% of our floor, with 44.56% of our coin in coming from them.

FY 2011 VGT machines made up 15.45% of our floor, with 48.65% of our coin in coming from them.

FY 2012 VGT machines made up 18.56% of our floor, with 52.27% of our coin in coming from them.

FY 2010 VGT machines averaged a hold % of 3.43%, while all other machines averaged a hold % of 7.43%.

FY 2011 VGT machines averaged a hold % of 3.15%, while all other machines averaged a hold % of 7.45%.

FY 2012 VGT machines averaged a hold % of 2.98%, while all other machines averaged a hold % of 7.33%.

### **Downstream Casino Hotel Phase II**

### Close-Out Meeting

### January 30, 2013

### Punch List Update:

- Total Punch List
  - 128 Pages
  - 4444 total items
  - Remaining
    - 6 1/2 pages
    - 187 items
    - 4.2%
- Before 1/1/13
  - 4103 items
  - 20 items remaining
  - .4%
- After 1/1/13
  - 341 items
  - 167 item's remaining
- New process for closing punch list items
- Completion Schedule:
  - All general items are scheduled to be completed by 2/8/13
    - +/- 45 days after Substantial Completion
  - Key Items / Exceptions:

ns/Exceptions:

9 Wood Ceiling - installing now; all materials on angles
Incomm - still working programming issues

Exterior Timers / Controls - trouble Shooting this week and then
train next

Valves @ Buffalo Grille ceiling - getting answers foolage

Decorative Glass - MONDOU

VWC Patches - released yesterday, starting this week.

Damaged Metal Panel (1) - from prase 1, ordered the new one
Others....

Control to for

Others....

Warranty Log: Controls on all much - Johnson Controls on site worker

MCC will maintain a warranty log separate from punch list completion On it, of

Official notifications to Matt Cook

### • Other Close-Out Topics:

- O Review "Close-Out" documents Summary
- O Review Attic Stock Summary review to make sure courts are accurate

### • Financial:

- o Review PCO Log / Outstanding Issues
- Review Backcharge Log
- o Other Issues:
  - Retainage
  - Release of balance of November pay application

# 143- Green Country \$ \$30,073

of Job - feel that it is not aconers responsibility

JCJ and Manhadlan to most and viewiew 1200 to separate on part of the costs.

\* charge back to subs from sules

Downstream Hotel Expansion 12049 SE 110th StreetGalena, KS 66739

## Potential Change Orders

Summary Log

Manhattan Construction Company Project # 3452 Tel: (620) 856-5600 Fax: (620) 856-5605

8495,783         CLOSED           0         0         0         CLOSED           0         0         0         CLOSED           0         0         0         CLOSED           0         0         0         CLOSED           63         19,683         19,683         NISC           0         0         0         CLOSED           0         0         <	PCO#	Description	Status	Order of Magnitude	Proposed Amount	Approved Amount	Impact on Contingency	Funded From Category	Additional Comments
International color of the co		₩			c	0	\$455,783	CLOSED	OMO legis of belonfood
Address Necestation of Particles and Parti	- '	Lithko - 3012-02-14 Core and Shell - Covered in Final GMIP	Closed		0	<b>S</b>	• •		Control of Control
Reminist State   Covered in Final GMP   Cooper   Cooper	7	Allen's Mechanical - Revised Pricing - Covered in Final GMP	Closed	•	<b>O</b> (	<b>&gt;</b> (	0	CLOSED	
State   Control of the Property   Control	ო	Bennett Steel Core and Shell Pricing - Covered in Final GMP	Closed	1	0	o	•	CLUSED	Included in Final GMIP
Parietin P1. Links and Bernett Steel - Covered in Final GMP	4	Faith Tech Core and Shell - Covered in Final GMP	Closed	•	0	0	0	CLOSED	Included in Final GMP
New Ord Dominger Repairs   19,863   19,863   19,863   19,863   19,863   19,863   19,863   19,863   19,864   1	30	Bulletin #1- Lithko and Bennett Steel - Covered in Final GMP	Closed	-	0	0	0	CLOSED	Included in Final GMP
Name of the Part	9	Road Damage Repairs	Closed	19,663	19,663	19,663	19,663	NISC	Approved by DDA
RFH 145 - Laber Date Nation Revisions - Covered in Final GMP	7	Mack Up Rooms	Closed	2,000	(2,042)	(2,042)	(2,042)	NISC	Approved by DDA
Registrate Layout vs. Existing Conditions - Covered in Final CMP   Closes   Closes	. 00	RFI #017 Foundation Revisions - Covered in Final GMP	Closed		0	0	0	CLOSED	Included in Final GMP
Public Hart Prock Doors Covered in Final GMP	, o.	REI #19 - Site Lavout vs. Existing Conditions - Covered in Final GMP	Closed	ı	0	0	0	CLOSED	Included in Final GMP
Modeles Road Repairs - Prairie Road Repairs - Prairie Road Repairs - Prairie Road Repairs - Prairie Road Road Repairs - Prairie Road Road Repairs - Prairie Road Road Road Road Road Road Road Road	. Q	Bulletin #2- Trash Truck Dock - Covered in Final GMP	Closed	ı	0	0	0	CLOSED	Included in Final GMP
100   100	1	Moates Road Repairs - Prairie Road	Closed		0	0	0	CLOSED	Work Paid Direct by Quapaw
1009/E Final Construction Deskings         Closed         796,160         (796,160)         (796,160)         (796,160)         (796,180)         (796,180)         (796,180)         (796,180)         Contingency           Dual Intrin at Retaining Wall         Bulletin at Retaining Wall         0.0854         3,260         0.0         0	12	RFI #31- Pier Depth Reconciliation	Closed	,	0	0	0	CLOSED	All cost added PCO #17
Displace   Parabeling Weal Buildent Weal Feature Weak Enricy Consisted   Costed Buildent #70 - Additional Ero Construction Design Drawings   Costed   18,739   18,739   18,739   18,739   18,739   18,739   18,739   18,739   18,739   18,730   18,730   18,770   18,7	13	100% Final Construction Drawings	Closed	(796,180)	(796,180)	(796,180)	(796,180)	Contingency	Buy-out Savings - Approved
Buildering Stroke Stability Strates and Obtionard at Existing Building Them         Classed         18,739         0         0         NISC           Buildering For Contraction to Personal Revisions Revisions and Work Point In Strates Leady Level Stab Readius and Work Point In Strates Leady Level Stab Readius and Work Point In Strates Leady Level Stab Readius and Work Point In Strates Leady Level Stab Readius and Work Point In Strates Leady Level Stab Readius and Work Point In Strates Leady Level Stab Readius and Work Point In Strates Leady Level Stab Readius and Work Point In Strates Leady Level Stab Readius and Work Point In Strates Leady Level Stab Readius and Work Point In Strates Leady Level Stab Readius and Work Point In Strates Leady Level Stab Readius and Work Point In Strates Leady Level Stab Readius and Point Revented In Strates Leady Level Stab Readius and Point Revented In Strates Leady Level Stab Readius Revisions In Door Hardware and Doors Frances Classed Rept Hirth 2.024 Level Revented Counter Revented Revented Level Revented Reve	4	Drain Tile at Retaining Wall	Closed	3,250	3,250	3,250	3,250	Contingency	Approved by DDA
Builletin #507 - Additional For Constituction Design Drawings         Closed         18,739         18,730         Confingency         Con	15	Budget for Demolition at Existing Building Tie-in	Closed	1	0	0	0	NISC	Issued on 11/28/12
Bulletin #30 - Foundations Modifications at West Entry Canopy (PCO #12)   Cosed 18,739   18,739   18,739   18,739   18,739   18,739   18,739   18,739   Sublicin #30 - Foundations Modifications at Work Point Cased 1,8,240   18,270   18,270   18,270   Confingency Port #30,240   18,270   Confingency Bulletin #30 - Provides Architectural Revisions   Cosed 1,640   1,640   1,640   1,640   1,640   1,640   Confingency Additional Fire Providing at Low Roof Above Lobby Woll	16	Bulletin #07 - Additional For Construction Design Drawings	Closed	•	0	0	0	CLOSED	Included in Final GMP
Part   1422   Cobby   Contingency   Closed   C	17	Bulletin #08 - Foundations Modifications at West Entry Canopy (PCO #12)	Closed	18,739	18,739	18,739	18,739	NISC/Cont'gy	Approved by DDA
Piex Floor Cover For Terrazzo   Cissed   18,270   18,27	18	RFI #82- Lobby Level Slab Radius and Work Point	Closed	3,849	3,849	3,849	3,849	Contingency	Approved by DDA
Equation   Formation   Forma	19	Flex Floor Cover For Terrazzo	Closed	18,270	18,270	18,270	18,270	Confingency	<ul> <li>Approved by DDA</li> </ul>
Epoxy Grout at Showers and Optional at Pool Area   Closed   VOID - All associated work Included in Bulletin #15   Contingency   VOID - All associated work Included in Bulletin #15   Countingency   VOID - All associated work Included in Bulletin #15   Countingency   VOID - All associated work Included in Bulletin #16   Closed   Close	20	Bulletin #09 - Provides Architectural Revisions	VOID	•	0	0	0	QIOA	Included in Final GMP
VOID - All associated work Included in Bulletin #15         VOID - All associated work Included in Bulletin #15         VOID - All associated work Included in Bulletin #15         VOID - All associated work Included in Bulletin #16         VOID - All associated work Included in Bulletin #16         VOID - All associated work Included in Bulletin #16         VOID - All associated work Included in Bulletin #16         VOID - All associated work Included in Bulletin #16         VOID - All associated work Included Incl	21	Epoxy Grout at Showers and Optional at Pool Area	Closed	31,152	31,152	31,152	31,152	Contingency	Approved by DDA
Alpha Additional Cost for Schedule         Closed Above Lobby         1,640         1,640         1,640         1,640         1,640         Ontingency On Ontingency On Ontingency On Ontingency On Ontingency On Ontingency On Ontingency Additional File Proofing at Low Roof Above Lobby         Additional File Proofing at Low Roof Above Lobby         Closed Closed Closed 10,702         2,328         2,328         Confingency Ontingency Ontingency Closed Closed 24,672         24,672         24,672         24,672         24,672         24,672         Confingency Contingency Contrigor Control Room Relocation to Penthouse Closed Closed Closed Special Additional File Tile Tile Tile Tile Tile Tile Tile T	22	VOID - All associated work included in Bulletin #15	VOID	1	0	0	0	VOID	
Additional Fire Proofing at Low Roof Above Lobby         VOID         Consideration         2,328         2,328         2,328         Confidency           RFI #113, Duckwork and VAV Interference with Electrical Rooms         Closed         10,702         10,702         10,702         10,702         10,702         Confingency           Bulletin #10- Revisions to Door Hardware and Doors Frames         Closed         24,677         24,677         24,677         Confingency           Proof and Whirlpool Clarifications         RFI #11 & 2,336         Elegan Clarifications         Closed         5,921         5,921         6,457         NISOr/Confingency           Proof and Whirlpool Clarifications         RFI #119 - Lobby Lounge Roof Details - Refer to Bulletin #15         VOID         2,632         5,921         6,947         0         VOID           Deletion of Walker Zanger Tile - Value Engineering         Closed         (12,214)         (12,	23	Alpha Additional Cost for Schedule	Closed	1,640	1,640	1,640	1,640	Contingency	Approved by DDA
RFI #113, Ductwork and VAV Interference with Electrical Rooms         Closed         2,328         2,328         Confingency           Bulletin #10- Revisions to Door Hardware and Doors Frames         Closed         10,702         10,702         10,702         10,702         24,672 <td< td=""><td>24</td><td>Additional Fire Proofing at Low Roof Above Lobby</td><td>VOID</td><td>,</td><td>0</td><td>0</td><td>0</td><td>diov</td><td></td></td<>	24	Additional Fire Proofing at Low Roof Above Lobby	VOID	,	0	0	0	diov	
RFI #117 & 236 - Elevator Control Room Relocation to Penthouse         Closed Closed         10,702 Closed         10,702 Closed         10,702 Closed         Contingency Closed<	25	RFI #113, Ductwork and VAV Interference with Electrical Rooms	Closed	2,328	2,328	2,328	2,328	Contingency	Approved by DDA
RFI #117 & 236 - Elevator Control Room Relocation to Penthouse         Closed Closed         24,672         24,672         24,672         24,672         Contingency (9,457)         Contingency (12,214)         Contingency (12,2	2 <sub>6</sub>	Bulletin #10- Revisions to Door Hardware and Doors Frames	Closed	10,702	10,702	10,702	10,702	Contingency	Approved by DDA
Pool and Whiripool Clarifications         Closed         (9,457)         (9,457)         (9,457)         (9,457)         NISC/Contgy           RFI #30 - Corridor Chair Rail and Trim Profile         Closed         5,921         5,921         5,921         5,921         5,921         Contingency           RFI #10 - Lobby Lounge Roof Details - Refer to Bulletin #15         VOID         0	27	RFI #117 & 236 - Elevator Control Room Relocation to Penthouse	Closed	24,672	24,672	24,672	24,672		Approved by DDA
RFI #30 - Corridor Chair Rail and Trim Profile         Closed         5,921         5,921         5,921         5,921         Contingency           RFI #19 - Lobby Lounge Roof Details - Refer to Bulletin #15         VOID         Closed         (35,840)         (35,840)         (35,840)         (35,840)         Confingency           Deleton of Walker Zanger Tile - Value Engineering         Closed         (12,214)         (12,214)         (12,214)         (12,214)         Confingency           Delete Steel Eyebrows and Add For Rework Existing Steel         Closed         (5,300)         (5,300)         (5,300)         (5,300)         (5,300)         Confingency           RFI #112 - Deduct for Spa support Slab Curbs         Bulletin #11 - Gas Line Resizing         T,549         T,549         T,549         T,549         Confingency           RFI #142, Buffalo Grille Wood Species Clarification         Closed         T,549	28	Pool and Whirlpool Clarifications	Closed	(9,457)		(9,457)			Approved by DDA
RFI #119 - Lobby Lounge Roof Details - Refer to Bulletin #15         VOID         -         VOID         VOID           Deletion of Walker Zanger Tile - Value Engineering         Closed         (35,840)         (35,840)         (35,840)         (35,840)         Contingency           Deletes Steel Eyebrows and Add For Rework Existing Steel         Closed         (12,214)         (12,214)         (12,214)         (12,214)         (12,214)         Contingency           RFI #112 - Deduct for Spa support Slab Curbs         Closed         -         0         0         0         CLOSED           Bulletin #11 - Gas Line Resizing         RFI #142, Buffalo Grille Wood Species Clarification         Closed         7,549         7,549         7,549         7,549         CLOSED           Bulletin #12 - Guest Roun Layout to Match Mock-Ups         Closed         7,549         7,549         7,549         7,549         7,549         Contingency           RFI #125 - Exhaust Fan #47 Deletion         VOID         NOID         NOID         NOID         NOID         NOID           RFI #105 - Exhaust Fan Wall Support Steel Changes - Refer to Bulletin #13 - Backflow Preventer Changes         Refer to Bulletin #14 - Revised Door Schedule         6,522         6,522         6,522         Contingency           Bulletin #14 - Revised Door Schedule         NOID         NOI	53	RFI #90 - Corridor Chair Rail and Trim Profile	Closed	5,921	5,921	5,921	5,921	Contingency	Approved by DDA
Deletion of Walker Zanger Tile - Value Engineering         Closed         (35,840)         (35,840)         (35,840)         (35,840)         Contlingency           Delete Steel Eyebrows and Add For Rework Existing Steel         Closed         (12,214)         (12,214)         (12,214)         (12,214)         (12,214)         (12,214)         (12,214)         (12,214)         Contlingency           RFI #112 - Deduct for Spa support Stab Curbs         Closed         -         0         0         0         CLOSED           Bulletin #11 - Gas Line Resizing         RFI #142, Buffalo Grille Wood Species Clarification         Closed         7,549         7,549         7,549         7,549         CLOSED           Bulletin #12 - Guest Rom Layout to Match Mock-Ups         VOID         VOID         0         0         0         0         0         0         0         VOID         VOID         NOID	30	RFI #119 - Lobby Lounge Roof Details - Refer to Bulletin #15	OIOV	•	0	0	0	NOID	Included in Final GMP
Delete Steel Eyebrows and Add For Rework Existing Steel         Closed         (12,214)         (12,214)         (12,214)         (12,214)         Contingency           RFI #112 - Deduct for Spa support Slab Curbs         Closed         (5,300)         (5,300)         (5,300)         (5,300)         Contingency           Bulletin #11 - Gas Line Resizing         -         0         0         0         CLOSED           RFI #142, Buffalo Grille Wood Species Clarification         Closed         7,549         7,549         7,549         7,549         CLOSED           Bulletin #11 - Gas Line Resizing         RFI #142, Buffalo Grille Wood Species Clarification         Closed         307,882         307,882         307,882         307,882         Contingency           RFI #125 - Exhaust Fan #47 Deletion         VOID         -         0         0         0         0         0         0         VOID         0         VOID	34	Deletion of Walker Zanger Tile - Value Engineering	Closed	(35,840)	(35,840)	(35,840)	(35,840)	_	Approved by DDA
RFI #112 - Deduct for Spa support Slab Curbs         Closed Closed         (5,300)         (5,300)         (5,300)         (5,300)         Contingency           Bulletin #11 - Gas Line Resizing         -         0         0         0         CLOSED           RFI #142, Buffalo Grille Wood Species Clarification         Closed         7,549         7,549         7,549         7,549         7,549         7,549         7,549         7,549         CutoSED           Bulletin #12 - Guest Room Layout to Match Mock-Ups         VOID         -         0         0         0         0         0         0         0         0         NOID         <	32	Delete Steel Eyebrows and Add For Rework Existing Steel	Closed	(12,214)	(12,214)	(12,214)	(12,214)	_	Approved by DDA
Bulletin #11 - Gas Line Resizing         Closed         -         0         0         CLOSED           RFI #142, Buffalo Grille Wood Species Clarification         Closed         7,549 <td>33</td> <td>RFI #112 - Deduct for Spa support Slab Curbs</td> <td>Closed</td> <td>(2'300)</td> <td>(5,300)</td> <td>(5,300)</td> <td></td> <td></td> <td>Approved by DDA</td>	33	RFI #112 - Deduct for Spa support Slab Curbs	Closed	(2'300)	(5,300)	(5,300)			Approved by DDA
RFI #142, Buffalo Grille Wood Species Clarification         Closed         7,549         7,549         7,549         7,549         Contingency           Bulletin #12 - Guest Room Layout to Match Mock-Ups         Closed         307,882         307,882         307,882         307,882         Contingency           RFI #125 - Exhaust Fan #47 Deletion         VOID         -         0         0         0         VOID           RFI #108 - Curtain Wall Support Steel Changes - Refer to Bulletin #13 - Backflow Preventer Changes         Refer to Bulletin #14 - Revised Door Schedule         6,522         6,522         6,522         6,522         Contingency           Bulletin #14 - Revised Door Schedule         VOID         -         0         0         VOID	34	Bulletin #11 - Gas Line Resizing	Closed		0	0	0	CLOSED	
Bulletin #12 - Guest Room Layout to Match Mock-Ups         Closed         307,882         307,882         307,882         Contingency           RFI #125 - Exhaust Fan #47 Deletion         VOID         -         0         0         0         VOID           RFI #108 - Curtain Wall Support Steel Changes - Refer to Bulletin #13 - Backflow Preventer Changes         Closed         6,522         6,522         6,522         6,522         Contingency           Bulletin #14 - Revised Door Schedule         VOID         -         0         VOID         VOID	35	RFI #142, Buffalo Grille Wood Species Clarification	Closed	7,549	7,549	7,549	7,549		Approved by DDA
RFI #125 - Exhaust Fan #47 Deletion       VOID       -       0       0       0       VOID         RFI #108 - Curtain Wall Support Steel Changes - Refer to Bulletin #13 - Bulletin #13 - Backflow Preventer Changes       Refer to Bulletin #15 - Bulletin #15 - Bulletin #14 - Revised Door Schedule       0       0       0       0       0       0       VOID	36	Bulletin #12 - Guest Room Layout to Match Mock-Ups	Closed	307,882	307,882	307,882	307,882	Contingency	Approved by DDA
RFI #108 - Curtain Wall Support Steel Changes - Refer to Bulletin #15         VOID         -         0         0         0         0         VOID           Bulletin #13 - Backflow Preventer Changes         6,522         6,522         6,522         6,522         6,522         Contingency           Bulletin #14 - Revised Door Schedule         VOID         VOID	37	RFI #125 - Exhaust Fan #47 Deletion	VOID	1	0	0	0	QiOA	
Bulletin #13 - Backflow Preventer Changes         Closed         6,522         6,522         6,522         6,522         Contlingency           Bulletin #14 - Revised Door Schedule         -         0         0         VOID	38	RFI #108 - Curtain Wall Support Steel Changes - Refer to Bulletin #15	VOID	•	•	0			
Bulletin #14 - Revised Door Schedule - 0 0 0 0 VOID	39	Bulletin #13 - Backflow Preventer Changes	Closed	6,522	6,522	6,522			Approved by DDA
	40	Bulletin #14 - Revised Door Schedule	NOID		0	0	0	NoiD	Cost Included in Bulletin #12

January 30, 2013

Jannary

January 30, 2013

Downstream Hotel Expansion 12049 SE 110th StreetGalena, KS 66739

## Potential Change Orders Summary Log

Manhattan Construction Company Project # 3452 Tel: (620) 856-5600 Fax: (620) 856-5605

# 000	- ;;-;		Order of	Proposed	Approved	Impact on	Funded From		
2	nescribinos.	smenc	Magnitude	Amount	Amount	\$455,783	Category	Additional Comments	
	RFI #187 - Balcony Support Angles Rework	Closed	14,985	14,985	14,985	14,985	Contingency	Approved by DDA	_
	Proposal to Add Wire Mesh at All Exterior Concrete Paving	Closed	13,760	13,760	13,760	13,760	Contingency	Approved by DDA	
	Overhead Door Custom Color Selection	Closed	2,760	2,760	2,760	2,760	Contingency	Approved by DDA	
84	Sauna and Steam Room Buyout	Pending	(25,000)	(41,223)	0	(25,000)	NISC BP13		
Ī	RFI #228 - ADA Bathroom Tile	Closed	6,065	6,065	6,065	6,065	Contingency	. Approved by DDA	_
	RFI #231 - Dishwasher Exhaust Duct	Closed	26,776	26,776	26,776	26,776	Contingency	Approved by DDA	_
87	Inncom Bid to Final Design Costs	8	606'2	606'2	7,909	606'2	Contingency		
	Fire Alarm Savings - EST Vs. Vigilant	(i) (i) (i)	(11,291)	(11,291)	(11,291)	(11,291)	Contingency		_
68	Bulletin #35 - Data Closet for Room L08	(6) St.	37,748	37,748	37,748	37.748	Contingency		_
	Overtime for Schindler Elevators on Elevator #3 & 4	Closed	30,712	30,712	30,712	30,712	Contingency	Approved by DDA	_
	RFI #239 - Relocation of BC-5	Closed	2,564	2,564	2,564	2,564	Contingency	Approved by DDA	_
	Bulletin #36 - Buffalo Patio Grille	io gg	4,581	4,581	4,581	4,581	Contingency		_
	Additional Attic Stock Materials	(i) (?)	39,014	39,014	39,014	39,014	Contingency		
	Traffic Doors Clarifications	Closed	3,835	3,835	3,835	3,835	Contingency	Approved by DDA	_
	Rift Cut Panels Vs. Plain Slice Panels	Closed	2,064	2,064	2,064	2,064	Contingency	Approved by DDA	_
	Bulletin #37 - Final design on Steam Generators	Closed	31,945	31,945	31.945	31.945	Contingency	Annived by DDA	_
26	Bulletin #38 - Pressure Reducing Value Station	Closed	26,324	26,324	26.324	26.324	Contingency	Approved by DDA	_
	RFI #265 - Banquet Kitchen Duct Revision	VOID	,	0	0		Contingency		_
	Buy-out Savings from NISC Log (PA#6 through 10)	Closed	(714,503)	(714,503)	(714,503)	(714,503)	Contingency	Approved by DDA	_
	RFI #264 - Birch Trees to Cedar Trees in Spa	Closed	(1,500)	(1,077)	(1,077)	(1,077)	Contingency	Approved by DDA	_
	Bulletin #39 - Milwork Alterations	Closed	5,711	5,711	5,711	5,711	Contingency	Approved by DDA	_
	RFI #278 & 279 - Roof Slope Clarifications	0.66	27,854	27,854	27,854	27,854	Contingency	in Constitution	
103	Projection Screen Support Materials	(1) SEL 35	569	269	569	569	Contingency		_
2	GCI Additional Overtime (Refer to PCO #143)	VOID	,	0		3	VOID		_
	Fire Proofing Patching - NISC	Closed	7,476	7,476	7.476	7.476	Contingency	Annroyed by DDA	_
	Manhattan Internal PCO	Closed	6,515	6,515	6.515	6.515	CLOSED	And by bearings	_
	RFI #282 - Rework Linear Diffuser at Artwork Area for Lights	Closed	8,410	8,410	8,410	8.410	Contingency	Annioused by O'C.	_
	RFI #295 - Bar Foot Rail at Lounge Bar	Closed	5,079	5,079	5,079	5.079	Continuency	And yet beyond,	_
	RFI #254, 296 & 324 - 2 & 3 Bay Suite Door Revisions	Closed	16,161	16,161	16.161	16.161	Contingency	And we beyond	_
130	RFI #297 - Window Mullion Add	Closed	•	0	0	C	Continuency	And we have not	_
	RFI #298 - Hotel Sales Miliwork Remake	Sevies	4,146	4,146	4.146	4 146	Continuency	COO to pooled	
	RFI #299 - Receptionist Desk Countertop Extensions	28.88	1,903	1,903	1,903	1,903	Contingency		
	RFI #300 - Elevator Lobby Cast Stone to Wall Covering	28:.88	1	0	0	0	Contingency		
	RFI #222 - Wood Fascia Change	VOID	•	0	0	0	VOID		
$\neg$	Frosted Glass Partitions in the Spa Bathrooms	Closed	11,100	11,100	11,100	11,100	Contingency	Approved by DDA	
	RFI #280 - Rework Linear Diffuser in Lobby (ADD TO PCO #107)	Closed	1	0	0	0	Contingency	Approved by DDA	
	STN-1003 Deletion and Wall Tile Add	Closed	•	0	0	0	Contingency	Approved by DDA	
	RFI #306 - Stair #03 Additional Rail	Closed	2,437	2,437	2,437	2,437	Contingency	Approved by DDA	_
	RFI #305 - Carpet Substitution	Closed	2,840	2,840	2,840	2,840	Contingency	Approved by DDA	_
120	Bulletin #40 - Pool Deck Clarifications	Closed	-	0	0	0	Contingency		_

January 30, 2013

Downstream Hotel Expansion 12049 SE 110th StreetGalena, KS 66739

### Potential Change Orders Summary Log

Manhattan Construction Company Project # 3452 Tel: (620) 856-5600 Fax: (620) 856-5605

# CO 	Description	Stafins	Order of	Proposed	Approved	Impact on Contingency	Funded From	Additional Comments	
			Magnitude	Amount	Amount	\$455,783	Category		
121	Deletion of the Guest Room Key Shelves		13,725	13,725	13,725	13,725	Contingency		
122	RFI #277 - Spa Floor Change at Rotunda and Steam Rooms	% 1/2	4,863	4,863	4,863	4,863	Contingency		
123	Main Spa Entry Door Height Conflict	Closed	5,235	5,235	5,235	5,235	Contingency	Approved by DDA	
124	Coil-up Door Header Rework	7	3,394	3,394	3,394	3,394	Contingency		
125	Bulletin #41 - Spa Mosaics	VOID	_	0	0	0	Contingency		
126	RFI #309 - Additional Lights in Foyer L04		715	715	715	715	Contingency		_
127	RFI 317 - Additional Point of Sales (POS)	53° 93	35,717	35,717	35,717	35,717	Contingency		
128	RFI #311 - Condenser Pump (CP-04) Additional VFD	Closed	7,166	7,166	7,166	7,166	Contingency	Approved by DDA	
129	Additional Countertop Cutting & Countertop Addition	6 X	1,822	1,822	1,822	1,822	Contingency		
130	RFI #325 - Additional Hotel Tower Corner Guards	Closed	13,137	13,137	13,137	13,137	Contingency	. Approved by DDA	
131	RFI #317 - Kitchen Power Modifications	[23] ලිනු	19,167	19,167	19,167	19,167	Contingency		_
132	RFI #243 - Exterior Sign Wood Blocking	Closed	14,763	14,763	14,763	14,763	Contingency	Approved by DDA	
133	RFI #310 - High Limits - CAT6 Homeruns and Additional Redundant Runs	(i.	12,993	12,993	12,993	12,993	Contingency		
134	RFI #329 - High Limits - REFER TO PCO #131	VOID	•	0	0	0	VOID		
135	High Limits - Additional Kitchen Power, Plumbing, Walls and Equipment	50.03	47,539	47,539	47,539	47,539	Contingency		
136	Additional Site Concrete	ns Sp	13,158	13,158	13,158	13,158	Contingency		
137	RFI #333 Additional TV's at Pool	e P	3,289	3,289	3,289	3,289	Contingency		
138	Project Caulking	6.	10,352	10,352	10,352	10,352	Contingency		
139	Site Electrical for Water Fountain	ią,	3,205	3,205	3,205	3,205	Contingency		
140	Bulletin #42 - Adding Reheat Coil to VAV 12-3	Closed	2,810	2,810	2,810	2,810	Contingency	Approved by DDA	
141	RFI #319 - High Limits Dimming Controls	VOID	2,700	0	0	0	Contingency		
142	Added Channel Support for Spa Wall Divider	VOID	,	0	0	0	Contingency		
143	Additional Cost - GCI	Reviewed	₹ 430,073	430,073	430,073	430,073	Contingency		_
<u>4</u>	Additional Cost - Miller Flooring	Reviewed	16,145	16,145	16,145	16,145	Contingency		
145	Additional Cost - Faith Technologies	Reviewed	29,295	29,295	29,295	29,295	Contingency		
146	Additional Cost - Allen's Mechanical	Reviewed	41,636	41,636	41,636	41,636	Contingency		-
147	Additional Cost - Fadco	Reviewed	1,983	1,983	1,983	1,983	Contingency		
148	Additional Cost - Reiss Painting	Reviewed	35,872	35,872	35,872	35,872	Contingency		
149	Additional Cost - Sprouls Construction	Reviewed	5,887	5,887	5,887	5,887	Contingency		
150	Additional Cost - American Terrazzo	Reviewed	4,459	4,459	4,459	4,459	Contingency		
151	Additional Cost - Tepco	Reviewed	•	0	0	0	Contingency		····
152	High Limits - Demolition Costs	(e. 3)	(7,000)	(7,122)	(7,122)	(7,122)	Contingency		
153	Additional Cost - Builders Supply	Reviewed	17,201	17,201	17,201	17,201	Contingency		
154	Additional Cost - Schindler	Reviewed	30,712	30,712	30,712	30,712	Contingency		
155	Spandrel Glass at Spa	128	2,000	2,000	2,000	2,000	Contingency		
156	Revisions to Bear and Scissor Tail Mosaics	Reviewed	2,662	2,662	2,662	2,662	Contingency		_
157	Trash Dumpsters - Final Costs	Reviewed	18,261	18,261	18,261	18,261	Contingency		
158	Temporary Labor and Final Cleaning - Final Costs	Reviewed	46,000	46,000	46,000	46,000	Contingency		
159			•	D	0	0			
160			•	0	0	0			

# **Manhattan**Building excellence.

Downstream Hotel Expansion 12049 SE 110th StreetGalena, KS 66739

# Potential Change Orders

Summary Log

Manhattan Construction Company Project # 3452 Tel: (620) 856-5600 Fax: (620) 856-5605

PCO#	Description	Status	Order of	Proposed	Approved	Impact on Contingency	Funded From	Additional Comments
			Magnitude	Amount	Amount	\$455,783	category	
161			1	D	0	0		
162			,	0	0	0		
163			•	0	0	0		
<u>\$</u>			•	0	0	0		
165			•	0	0	0		
	Project Totals:		741,205	614,420	655,643	(174,860)		